


Purchase a Metal EDM Surface Finish Gage –
 Send PO and Check for \$300. with your UPS Collect or Fed-EX Collect acct. #
 Or send \$310. Which includes Ground shipment within USA to:

High Performance Machinery, LLC

2967 Chestnut Hill Ave

Athol, MA. 01331

978-204-6501



AGIECHARMILLES EDM SURFACE FINISH CROSS REFERENCE CHART

EDM Surface Finish Scale	RA MICRO-METER	RA MICRO INCHES	RMS
-2	.08	3.14	3.90
-1	.09	3.54	4.40
0	.10	3.94	4.90
1	.11	4.33	5.50
2	.12	4.72	5.90
3	.14	5.51	6.90
4	.16	6.29	7.90
5	.18	7.09	8.90
6	.20	7.87	9.90
7	.22	8.66	10.80
8	.25	9.84	12.3
9	.28	11.02	13.80
10	.32	12.60	15.80
11	.35	13.78	17.20
12	.40	15.60	19.50
13	.45	17.6	22.00
14	.50	19.60	24.50
15	.56	21.60	27.00
16	.64	25.00	31.30
17	.72	28.10	35.20
18	.80	31.20	39.00
19	.91	35.50	44.40
20	1.01	39.40	49.30
21	1.12	43.70	54.60
22	1.28	49.90	62.40
23	1.44	56.20	70.30
24	1.60	62.40	78.00
25	1.81	70.60	88.20
26	2.03	79.10	98.90
27	2.24	87.40	109.20
28	2.54	99.10	123.90
29	2.84	110.80	138.50
30	3.15	122.9	153.70
31	3.6	140.40	175.50
32	4.05	158.00	197.50
33	4.50	175.50	218.80
34	5.10	198.90	248.60
35	5.70	222.30	277.90

Call High Performance Machinery 978-204-6501 for more information

Surface Finishes

Measurement of surface finishes is done with instruments called profilometers.

Experience proves that measurement of surface finishes by comparison using a surface finish gauge does not give an error above 2 CH classes.

The criteria of roughness are the Ra (Europe) – CLA (UK) – AA (USA)

To obtain a grading of roughness, Charmilles has defined a CH scale, which is however cross referenced with the standards that are in common use.

VDI 3400	Ra = CLA = AA		class
AGIE CHARMILLES	µm	µ inch	ISO 1302
0	0,10	4,0	N3
1	0,11	4,4	
2	0,12	4,8	
3	0,14	5,0	
4	0,16	6,4	
5	0,18	7,2	
6	0,20	8,0	N4
7	0,22	8,8	
8	0,25	10,0	
9	0,28	11,2	
10	0,32	12,8	
11	0,35	14,0	
12	0,40	16,0	N5
13	0,45	18,0	
14	0,50	20,0	
15	0,56	22,4	
16	0,63	25,2	
17	0,70	28,0	
18	0,80	32,0	
19	0,90	36,0	N6
20	1,00	40,0	
21	1,12	44,8	
22	1,26	50,4	
23	1,40	56	
24	1,62	63	
25	1,80	72	N7
26	2,00	80	
27	2,20	88	
28	2,50	100	
29	2,80	112	
30	3,20	125	N8
31	3,50	140	
32	4,00	160	
33	4,50	180	
34	5,00	200	
35	5,60	224	
36	6,30	250	N9
37	7,00	280	
38	8,00	320	
39	9,00	360	
40	10,00	400	
41	11,20	448	
42	12,60	500	N10
43	14,00	560	
44	16,00	640	
45	18,00	760	

Definition of Roughness criteria

No CH = $20 \log (10 Ra) (\mu m)$

Some significant rules and figures

1 µm Ra = CH20

10 µm Ra = CH40

If Ra = Ra x 2 → CH = CH+6

ex: 1 µm Ra = CH20

2 µm Ra = CH26

3 µm Ra = CH32

The ratio

between 2 successive CH units is 1.12

The difference

between 2 successive CH units is 12.2%

The MAX Rt: roughly equal to 8 x Ra

The mean Rt: is the arithmetic mean of the 5 Max Rt recorded on the 5 sample lengths selected.

(For establishing the technology: 0.8mm)

Mean Rt = 5 x the Ra value

Note:

In surface finish measurements a tolerance of + 2 CH units is accepted.

Further note:

The American and English standards admit the following relationship between the values V(RMS) and V(Ra):

$$\underline{V(RMS) = 1.11 V(Ra)}$$

The French standard **NF 05051** is tied in with the **ISO 1302** standard concerning classes of surface finish.

Call High Performance Machinery for all New and Used Machinery needs:

- High Speed Milling
- Wire EDM
- Sinker EDM
- 3D Printing both Metals & Plastics
- Holepopper EDM Drill
- Precision Grinding
- Engraving machines

John Griffiths at: 978-204-6501